

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio.

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio.

Source: <http://linux.derkeiler.com/Mailing-Lists/Fedora/2006-11/msg01299.html>

- *From:* Dario Lesca <d.lesca@xxxxxxxxxxx>
 - *Date:* Mon, 06 Nov 2006 11:34:09 +0100
-

Il giorno dom, 05/11/2006 alle 17.25 -0200, Vinicius ha scritto:

Vinicius escreveu:

Ric Moore escreveu:

On Fri, 2006-11-03 at 01:48 -0300, Vinicius wrote:

Ric Moore escreveu:

On Wed, 2006-11-01 at 10:31 -0300, Vinicius wrote:

Hello,

The sound card is always on.

When the webcam is on, the volume control shows only microphone control and there is no option to change to the sound card.

When the webcam is

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio.

off, the
system
recognizes
the sound
card, so
it's
displayed at
volume
control, that
way I can
hear sound.

Any ideas
to solve this
issue,
please?

I've not had my webcam
work since the latest kernel
2200
How do you get yours to
work? Ric

Hello,

I been using the pwc driver with success on
FC5, but until now I
haven't success to build the driver again on
FC6.

That's maddening. Like you I could build the module with no
sweat before
and now it refuses to build with some problem in the kernel,
I think.
Not sure though. Ric

In the pwc's mailing list says the version 10.0.12 is inside the kernel
2.6.18.

But I don't know how to use it, yet.

Cheers,
Vinicius.

From the PWC's mailing list (tip from Luca Capello):

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio

Re: Problem between Webcam Logitech Pro 4000's microphone and sound card Intel 82801BA AC'97 Audio.

1. Check if it's compiled by default:

=====

```
$ grep PWC /boot/config-2.6.18*
```

```
CONFIG_USB_PWC=m
```

```
# CONFIG_USB_PWC_DEBUG is not set
```

=====

2. Depending of the CONFIG_USB_PWC value: if it's 'y' the driver is compiled into the kernel and so it's always available (no need to insert the module).

If it's 'm' (which is normally the mostly seen situation for ke