

## Etch issues with HP Netraid 2M

---

*Source:* <http://linux.derkeiler.com/Mailing-Lists/Debian/2007-04/msg04830.html>

---

- *From:* "Brian Morton" <[rokclimb15@xxxxxxxxxx](mailto:rokclimb15@xxxxxxxxxx)>
  - *Date:* Mon, 30 Apr 2007 15:14:39 -0400
- 

I am having terrible issues trying to install Etch on my server using this SCSI RAID controller. The controller is detected and megaraid\_mbox and megaraid\_mm are loaded, but GRUB fails to install and LILO installs, but does a repeated EOF message on reboot. I have tried manually removing the modules for megaraid\_mbox and megaraid\_mm and instead loading the legacy megaraid, but the controller is not detected in that case. Although partitioning, etc. appear to work under the newer megaraid\_mbox module, it seems there is some sort of problem with my controller. This hardware setup functioned with no issues under a 2.4 kernel. This problem could be related to bug #317258, but I am not sure. Can anyone offer any insight into this problem? I have a feeling it is a known issue, I just want to confirm and see if there is a work-around. Thanks!