

Re: spac5xx driver

Source: <http://linux.derkeiler.com/Mailing-Lists/Fedora/2006-03/msg06098.html>

- *From:* Eric Tanguy <eric.tanguy@xxxxxxxxxxxxxxxx>
 - *Date:* Thu, 30 Mar 2006 23:14:23 +0200
-

Le mercredi 29 mars 2006 à 22:48 +0200, Eric Tanguy a écrit :

This driver compile fine with the new 2.6.16 kernel and the module loads fine but when i try to watch the output of the webcam using camstream i can see the images 1 or 2 seconds and the system reboot!

Someone experience the same thing ?

lsusb :

Bus 003 Device 001: ID 0000:0000

Bus 002 Device 002: ID 04b8:011f Seiko Epson Corp. Perfection 1670

Bus 002 Device 001: ID 0000:0000

Bus 001 Device 002: ID 041e:401c Creative Technology, Ltd WebCam NX [PD1110]

Bus 001 Device 001: ID 0000:0000

this driver and this camera on the same system worked fine with fc4.

Eric

No one use this driver ?

Eric

fedora-list mailing list

fedora-list@xxxxxxxx

To unsubscribe: <https://www.redhat.com/mailman/listinfo/fedora-list>