

[2.6.10-rc1-mm2] Firmware loader gone bogus?

Source: <http://linux.derkeiler.com/Mailing-Lists/Kernel/2004-10/10338.html>

From: Christian Axelsson (*smiler_at_lanil.mine.nu*)

Date: 10/31/04

Date: Sun, 31 Oct 2004 20:51:28 +0100

To: linux-kernel@vger.kernel.org

Ive upgraded from 2.6.9-rc4-mm1 to 2.6.10-rc1-mm2 and now the firmware loader seems broken. I have an internal wlan-adaptor that runs the ipw2200-driver and I get errors when trying to load the firmware. Then I tried my prism54-based card and got the following errors in dmesg:

```
Loaded prism54 driver, version 1.2
PCI: Enabling device 0000:03:00.0 (0000 -> 0002)
ACPI: PCI interrupt 0000:03:00.0[A] -> GSI 6 (level, low) -> IRQ 6
eth1: resetting device...
eth1: uploading firmware...
prism54: request_firmware() failed for 'isl3890'
eth1: could not upload firmware ('isl3890')
eth1: islpci_reset: failure
```

The firmware files are in place and both these cards with drivers have worked fine before. Config attached

--

Regards,
Christian

-

To unsubscribe from this list: send the line "unsubscribe linux-kernel" in the body of a message to majordomo@vger.kernel.org

More majordomo info at <http://vger.kernel.org/majordomo-info.html>

Please read the FAQ at <http://www.tux.org/lkml/>

- application/gzip attachment: [config.gz](#)