

## RHEL 4 with HP ML150 G3 install problem: two drives displayed instead the raid drive

---

*Source:* <http://linux.derkeiler.com/Mailing-Lists/RedHat/2007-05/msg00226.html>

---

- *From:* "Salvador Santander Gutierrez" <[salvador.santander@xxxxxxxxxxxxxxxxxxxxxx](mailto:salvador.santander@xxxxxxxxxxxxxxxxxxxxxx)>
  - *Date:* Tue, 22 May 2007 18:59:22 +0200
- 

Hello list.

We've a problem installing RHEL 4 U5 in a HP Proliant ML150 G3. It seems to be a problem with the raid controller, because when we want partition the disk, two drives appears instead of one (only the logical raid 1 drive). The raid 1 has been created and verified.

In the installation notes we've seen that to get RHEL 4 installation recognize the driver, we have to use linux dd command at the prompt of installation but we didn't find how to make the driver disk and tell with the 'linux dd' command where to find the driver.

We basically needs how to:

- make the driver disk
- sintaxis of linux dd command

Or another solution if you know how to solve this problem.

Thanks in advance.

—

redhat-list mailing list  
unsubscribe <mailto:redhat-list-request@xxxxxxxxxx?subject=unsubscribe>  
<https://www.redhat.com/mailman/listinfo/redhat-list>