

Re: Wireless Fix for IPW 2200's on Laptops after upgrade to 2.6.17-1.2139

Source: <http://linux.derkeiler.com/Mailing-Lists/Fedora/2006-06/msg04992.html>

- *From:* Matthew Saltzman <mjs@xxxxxxxxxxxxxxxx>
 - *Date:* Fri, 30 Jun 2006 13:43:09 -0400 (EDT)
-

On Fri, 30 Jun 2006, Jonathan Underwood wrote:

On 30/06/06, Ed Gurski <ed@xxxxxxxx> wrote:

My Intel Pro Wireless 2200BG required the latest firmware drivers to be installed. (<http://www.ces.clemson.edu/linux/fc2-ipw2200.shtml>).

Just follow the instructions, reboot and it will be working...

Note: You may not see the wireless indicator lit, but as soon as you connect through Network Manager, it will light-up...

Are you sure that's all necessary? I have a ipw2200 system which just worked with the new kernel without doing any of that.

It seems to work reliably enough out of the box, but there are some useful patches in the latest drivers. You can probably live without them in most cases, but if NetworkManager gives trouble, they are worth a try.

--

Matthew Saltzman

Clemson University Math Sciences
mjs AT clemson DOT edu
<http://www.math.clemson.edu/~mjs>

--

fedora-list mailing list
fedora-list@xxxxxxxx
To unsubscribe: <http://www.redhat.com/mailman/listinfo/fedora-list>