

Re: 2.6.0-test2, sensors and sysfs

Source: <http://linux.derkeiler.com/Mailing-Lists/Kernel/2003-07/3336.html>

From: Tomasz Torcz (zdzichu_at_irc.pl)

Date: 07/31/03

Date: Thu, 31 Jul 2003 19:21:41 +0200

To: LKML <linux-kernel@vger.redhat.com>

On Flameeyes wrote:

- > *I tried either with i2c-viapro and via686a as modules, and built-in in*
- > *kernel. Nothing changes. Also dmesg doesn't output anything.*
- > *I have missed something?*

Be aware that via686 (and i2c-isa and probably others) do not work when compiled into kernel. It must be in a module.

--

Tomasz Torcz "Never underestimate the bandwidth of a station wagon filled with backup tapes." -- Jim Gray

|> Playing: Negative.10.31.02 ...

-

To unsubscribe from this list: send the line "unsubscribe linux-kernel" in the body of a message to majordomo@vger.kernel.org

More majordomo info at <http://vger.kernel.org/majordomo-info.html>

Please read the FAQ at <http://www.tux.org/lkml/>