

Linux-Kernel: Fwd: Toshiba PS/2 touchpad on 2.6.X not working along bottom and right sides

Fwd: Toshiba PS/2 touchpad on 2.6.X not working along bottom and right sides

Source: <http://linux.derkeiler.com/Mailing-Lists/Kernel/2004-12/6246.html>

From: Andrew Haninger (*ahaning_at_gmail.com*)

Date: 12/30/04

Date: Thu, 30 Dec 2004 09:58:06 -0500

To: linux-kernel@vger.kernel.org

I forgot to CC the list in case anyone else was interested in this information as well.

Sorry about the dupe, Dmitry.

—Andy

----- Forwarded message -----

From: Andrew Haninger <ahaning@gmail.com>

Date: Thu, 30 Dec 2004 09:53:33 -0500

Subject: Re: Toshiba PS/2 touchpad on 2.6.X not working along bottom and right sides

To: Dmitry Torokhov <dtor_core@ameritech.net>

> > *I recently installed Linux 2.6.10 on my Gateway Solo 2500 notebook*
> > *after using it happily with 2.4.27 (aside from some ACPI sleeping*
> > *issues). Since installing the new kernel, I've noticed an odd problem*
> > *with the Toshiba PS/2 touchpad which is used as a cursor. If I move my*
> > *finger left and right along the 'bottom' portion of the touchpad or up*
> > *and down along the right side, there is no movement from the mouse*
> > *cursor at all. This behavior shows up using gdm and XFree86. Running*
> > *'xev' produces no output when these sides are used. However, if I move*
> > *my finger left-right along the top side or up-down along the left*
> > *side, the cursor moves just fine. Tapping the pad to click in the*
> > *non-working areas and moving the finger from outside of these areas*
> > *and then into them, however, works fine*
>
> *What does dmesg and /proc/bus/input/devices say about your touchpad?*

```
root@laptop:~# dmesg | grep "PS"
```

```
mouse: PS/2 mouse device common for all mice
```

```
input: PS2T++ Logitech TouchPad 3 on isa0060/serio1
```

```
root@laptop:~# cat /proc/bus/input/devices
```

```
I: Bus=0011 Vendor=0002 Product=0003 Version=0061
```

Fwd: Toshiba PS/2 touchpad on 2.6.X not working along bottom and right sides

Linux-Kernel: Fwd: Toshiba PS/2 touchpad on 2.6.X not working along bottom and right sides

N: Name="PS2T++ Logitech TouchPad 3"
P: Phys=isa0060/serial/input0
H: Handlers=mouse0
B: EV=7
B: KEY=70000 0 0 0 0 0 0 0
B: REL=143

Actually, this was more information than I was able to find earlier.
I'll be able to do some more useful searches now.

Thanks.

--

Andy

-

To unsubscribe from this list: send the line "unsubscribe linux-kernel" in
the body of a message to majordomo@vger.kernel.org

More majordomo info at <http://vger.kernel.org/majordomo-info.html>

Please read the FAQ at <http://www.tux.org/lkml/>