

w83791d sensor support

Source: <http://linux.derkeiler.com/Mailing-Lists/Kernel/2006-01/msg11482.html>

- *From:* Charles Spirakis <bezaur@xxxxxxxxxx>
 - *Date:* Tue, 31 Jan 2006 10:21:29 -0800
-

All --

I noticed the w83791d chip is supported in 2.9.2 of lm_sensors (in .../chips/w83781d.c) but that it isn't supported in the 2.6 kernel (.../drivers/hw_mon/w83781d.c).

Does anyone know why? From what I can see in the lm_sensor's archive, the support was added to lm_sensors around may of 2003.

Is there any interest in having support for the w83791d in the kernel driver?

-- charles

-

To unsubscribe from this list: send the line "unsubscribe linux-kernel" in the body of a message to majordomo@xxxxxxxxxxxxxxxx
More majordomo info at <http://vger.kernel.org/majordomo-info.html>
Please read the FAQ at <http://www.tux.org/lkml/>

- Prev by Date: [***Re: \[OT\] 8-port AHCI SATA Controller?***](#)
- Next by Date: [***Re: \[PATCH\] RealTek RTL-8169 Full Duplex Patch***](#)
- Previous by thread: [***2.6.16rc1-git4 slab corruption.***](#)
- Next by thread: [***\[PATCH\] amd76x pm: C3 powersaving for AMD K7***](#)
- Index(es):
 - ◆ [***Date***](#)
 - ◆ [***Thread***](#)