

## solved Re: 2.6.20 SATA error

---

*Source:* <http://linux.derkeiler.com/Mailing-Lists/Kernel/2007-02/msg10251.html>

---

- *From:* Gerhard Mack <gmack@xxxxxxxxxxxxxx>
  - *Date:* Wed, 28 Feb 2007 16:55:32 -0500 (EST)
- 

On Wed, 28 Feb 2007, Charles Shannon Hendrix wrote:

On Wed, 28 Feb 2007 13:25:00 -0500 (EST)  
Gerhard Mack <gmack@xxxxxxxxxxxxxx> wrote:

In another thread, I think they were saying it was either a  
SATA chipset  
driver bug, or a problem in libata core.

I also have an nforce4.

On another mailing list, someone with an Intel chipset is reporting the same  
problem, and also that others without nforce chipsets are seeing it.

I was reaching inside my computer to check something and heard the thing  
click and got the same error message.

Turns out the adaptor that goes between SATA drive and the old style power  
connector was loose on the drive side. Doesn't seem to me like it was  
very snug fitting to begin with. I changed it to one of the proper SATA  
connectors coming off the power supply and it doesn't do that anymore.

Sorry for the false alarm,

Gerhard

--

Gerhard Mack

gmack@xxxxxxxxxxxxxx

<>< As a computer I find your faith in technology amusing.

-

solved Re: 2.6.20 SATA error

To unsubscribe from this list: send the line "unsubscribe linux-kernel" in the body of a message to majordomo@xxxxxxxxxxxxxxxxx  
More majordomo info at <http://vger.kernel.org/majordomo-info.html>  
Please read the FAQ at <http://www.tux.org/lkml/>